

← sensor

leistung

50%25%
25%12,5%
75%37,5%
0%0%minmax100%50%

notaus

← 12V= 3A

an

laser akt.

cnc stop

status

menu

Pnorm

seite

Pmin

laser an/aus
(h triger bei Pmin)

12V+
12V+
GND
GND
AGND
5V+
NC
I2C
I2C

laser

12V= 3A

ext. trigger 10kΩ
open collector

pubo
pubo
pubo

12V+
12V+
GND
GND
AGND
5V+
NC
I2C
I2C

laser

12V= 3A

ext. trigger 10kΩ
open collector

pubo
pubo
pubo

cw-Laser Ansteuerung PLH3D-6W

12V+
12V+
GND
GND
AGND
5V+
NC
I2C
I2C

laser 12V= 3A
+ -

ext. trigger 10kΩ
open collector
pubo
pubo
pubo

